


**C** 1 855 535 0558

🔊 cprosolutions.com

## **ASSEMBLY - GLADIATOR RAIL SYSTEM**



CONNECT WELD-MENT FRAME & WELDMENT UPRIGHT TOGETHER AS THE FIGURE ILLUSTRATES.

**TIGHTEN BOLTS &** NUTS TOGETHER USING A 3/4" WRENCH\* TO FIRMLY INSTALL THE TWO PARTS.

## STEP 2

MECHANICAL **JACKS:** 

CONNECT THE **MECHANICAL JACKS** TO EACH SIDE OF THE WELDMENT UPRIGHT AS THE DIAGRAM SHOWS. USE PINS TO LOCK TOGETHER.

1



## **ASSEMBLY - GLADIATOR RAIL SYSTEM**

