




Rolling Bench


Kit B

Assembly instructions



Kit - Start

It's important to always start with Kit B when you start building a new table.



Kit - Warning













Take note that before you screw the table in the floor you have to:

- **Level the entire table**
- **Adjust the water dripping slope**
- **Adjust the length of the Kit B**
- **Make sure that the top of the table is in straight line**

Part Qty Description

# 1	X13	Mounting Nut (M6)	
# 2	X9	Mounting Bolt (M6*55L)	
# 3	X68	Mounting Bolt (M6*18L)	
# 4	X65	Mounting Washer	
# 5	X2	Square Bar (Short)	
# 6	X2	V-Shape Bar	
# 7	X8	Mounting Bolt (M6*8L)	
# 8	X4	Square Bar (Long)	
# 9	X8	Small Plastic Piece	
# 10	X2	Rolling Bar Kit B	
# 11	X2	Metal Trust With Side Holes	
# 12	X4	Metal Trust	
# 13	X8	Right Angle Metal Connector	
# 18	X4	Straight Metal Connector	
# 19	X1	Turnable Handle	
# C-1	X4	U-Shape Part (Long)	
# C-2	X4	U-Shape Part (Short)	

Part Qty Description


# A1	X2	Right Angle Plastic Connector	
# B1	X2	Right Angle Plastic Connector	
# B2	X2	Straight Plastic Connector	
# B4	X4	Leg	
# B-R	X1	Right Aluminum Side	
# B-L	X1	Left Aluminum Side	
# A-A	X1	Aluminum Side	
# B-B	X1	End Aluminum Side	
# 20	X16	Plastic Cap (41*41)	
# 21	X8	Square Plastic Cap (30*30)	
# 22	X2	Round Plastic Cap (D=42)	
# 23	X1	Round Plastic Cap (D=38)	

Also includes assembly tools:




- Hex Wrench 4mm (x2) 
- Open-Ended Wrench 10mm (x2) 

Kit B - Parts



Part Qty


# 1	X6	
# 2	X4	
# 3	X6	

Part Qty

# 4	X4	
# 5	X1	
# 6	X1	

Part Qty

# B4	X2	
# C-2	X2	



Kit B - Step 1

Part Qty

3 X4



4 X4



Part Qty

8 X4



9 X4



Part Qty


21 X16



X1



X4



Kit B - Step 2

Part Qty

3 X4

4 X4




Part Qty

9 X4



Part Qty


X1



Kit B - Step 3

Part Qty

20 X12



Kit B - Step 4


Part Qty

10 X2



Part Qty

22 X2



Kit B - Step 5

Part Qty

3 X12



4 X12



Part Qty

11 X2



12 X4





Part Qty

B-R X1



B-L X1



Kit B - Step 6


Part Qty

B1 X2



Part Qty

B-B X1



NOTE: Angle Plastic Connectors
A1 and End Aluminum Sides
A-A must be kept apart for Kit A.

Kit B - Step 7

Part Qty

3 X12

4 X12




Part Qty

13 X4



Part Qty

X1



Kit B - Step 8

Part Qty

3 X8




Part Qty

4 X8




Part Qty

B2 X2




Use typ #3 screws if the table surface of Kit B is used at its full length (6'). If not, you need to use the typ #7 screws instead of the typ #3 screws.

7 X8



Kit B - Step 9



Kit B - Step 10

Part Qty

3 X8






Part Qty

4 X8



Part Qty












C-1 X4



Kit B - Step 11

Remains Parts

The remaining parts need to be used to close the table when the length is determined. The steps of the assembling of those parts are illustrated in the Kit's A booklet.

Part	Qty	Description		Part	Qty	Description	
# 1	X1	Mounting Nut (M6)		# 19	X1	Turnable Handle	
# 2	X1	Mounting Bolt (M6*55L)		# A1	X2	Right Angle Plastic Connector	
# 3	X12	Mounting Bolt (M6*18L)		# A-A	X1	Aluminum Side	
# 4	X13	Mounting Washer		# 20	X4	Plastic Cap (41*41)	
# 13	X4	Right Angle Metal Connector		# 23	X1	Round Plastic Cap (D=38)	
# 18	X4	Straight Metal Connector					

Keep those parts for Kit A's booklet.

IMPORTANT NOTE


Plastic tray with drain
must always be
installed on Kit B.



Rolling Bench


Kit A

Assembly instructions



Kit - Start



















It's important to always start with Kit B when you start building a new table.



Kit - Warning

Take note that before you screw the table in the floor you have to :

- Level the entire table
- Adjust the water dripping slope
- Adjust the length of the Kit B
- Make sure that the top of the table is in straight line




Part	Qty	Description	Part	Qty	Description
# 1	X8	Mounting Nut (M6) 	# A1	X2	Right Angle Plastic Connector 
# 2	X6	Mounting Bolt (M6*55L) 	# A2	X2	Straight Plastic Connector 
# 3	X54	Mounting Bolt (M6*18L) 	# A4	X2	Leg 
# 4	X50	Mounting Washer 	# A-R	X1	Right Aluminum Side 
# 6	X1	V-Shape Part 	# A-L	X1	Left Aluminum Side 
# 11	X1	Metal Trust With Side Holes 	# C-1	X2	U-Shape Part (Long) 
# 12	X5	Metal Trust 	# C-2	X2	U-Shape Part (Short) 
# 14	X1	Square Bar (Short) 			
# 15	X4	Square Bar (Long) 			
# 16	X2	Rolling Bar of Kit A 			
# 17	X4	AA Straight Metal Connector 			

Also includes assembly tools:




- Hex Wrench 4mm (x2) 
- Open-Ended Wrench 10mm (x2) 

Kit A - Parts

Part Qty



# 1	X6	
# 2	X4	
# 3	X6	

Part Qty

# 4	X4	
# 6	X1	
# 14	X1	

Part Qty

# A4	X2	
# C-2	X2	



Kit A - Step 1

Part Qty

3 X8

4 X8




Part Qty

15 X4



Part Qty

X1



Kit A - Step 2

Part Qty

#3 X8




Part Qty

#4 X8



Part Qty

X1



Kit A - Step 3

Part Qty

1 X2



2 X2





Part Qty

4 X2



Part Qty

16 X2



Kit A - Step 4

Part Qty

3 X12



4 X12



Part Qty

11 X1



12 X5






Part Qty

A-R X1



A-L X1



Kit A - Step 5

Part Qty

3 X8



4 X8



Part Qty

18 X4






Part Qty

X1



* For more informations, go to the **Kit A - Details** page.



Kit A - Step 6


Part Qty

3 X4



Part Qty

C-1 X2



Kit A - Step 7

Part Qty

3 X8



4 X8



Part Qty

17 X4



A2 X2




Part Qty

X1




* For more informations, go to the **Kit A - Details** page.




Repeat steps 1 to 7 for adding Kits A as much as you want. connect these benches by using the Straight Plastic Connectors between them.

A2 X2



Kit A - Step 8




Kit A + Kit A

Use Straight Plastic Connectors (A2) to connect all the Kit A together.

Kit A + Kit B


Use Straight Plastic Connectors (B2) to connect a Kit A and a Kit B together.



Kit A + Kit A

Use Straight Metal Connectors (#17) to connect all the Kit A together.

17 X4



Kit A + Kit B

Use Straight Metal Connectors (#18) to connect a Kit A and a Kit B together.

18 X4



Kit A - Details

Part Qty

3 X4



4 X4



Part Qty

13 X4




A-A X1



Part Qty

A1 X2



Kit A - Step 9

Part Qty

3 X8





Part Qty

4 X8



Part Qty

X1



Kit A - Step 10

Part Qty

1 X1



2 X1



Part Qty

4 X1




19 X1



Part Qty


23 X1




Kit A - Step 11

Part Qty

20 X4




Kit A - Step 12




* Unscrew the Straight Plastic Connectors bolts and the second leg bolts.


Kit B - Adjustment




Kit B - Adjustment





Kit B - Adjustment





* If you want to re-screw the Straight Plastic Connectors bolts and the second leg bolts we suggest using self-tapping screws (not included).





Kit B - Adjustment





**Kit A + Kit B
Minimum length**



Kit A - 4'



**Kit A + Kit B
Minimum length**



**Kit A + Kit B
Maximum length**

Kit A - 5'

Parts from Kit B

The remaining parts need to be used to close the table when the length is determined.

Part	Qty	Description		Part	Qty	Description	
# 1	X1	Mounting Nut (M6)		# 19	X1	Turnable Handle	
# 2	X1	Mounting Bolt (M6*55L)		# A1	X2	Right Angle Plastic Connector	
# 3	X12	Mounting Bolt (M6*18L)		# A-A	X1	Aluminum Side	
# 4	X13	Mounting Washer		# 20	X4	Plastic Cap (41*41)	
# 13	X4	Right Angle Metal Connector		# 23	X1	Round Plastic Cap (D=38)	
# 18	X4	Straight Metal Connector					